

305404 Ci IV8 Service kit box

General

The service kit box contains all the parts which can be replaced by the service technician on the Ci IV8 valve.

Each room in the box is marked with item number.

It contains items for resetting app. 10 pcs. Ci IV8 valves.


Special tools for resetting the Ci IV8 valve must be purchased separately (item 305402, Tool kit Control Inert).

Lubricant Krytox (203062) is the only one that may be used for the piston (305403).

Other lubricants e.g., formerly used OHA (203008), may be applied on static O-rings.

Content of the service kit box:

Item no.	Name	Qty
203062	Lube: Krytox GPL 205 6gr	1
212181	Seal Cu 1/4" Manometer	5
212221	Screw M5x6 Pinol with tip A2	10
214009	Seal Red	10
214010	Seal wire coarse RS (a'250mm)	10
2071166	O-ring 7.1x1.6 Z24 - P5001	10
2141162	O-ring 14.1x1.6 PU90	10
2171162	O-ring 17.1x1.6 PU75	10
2061162	O-ring 6.1x1.6 PU75	10
2251162	O-ring 25.1x1.6 PU75	10
305098	Washer $\varnothing 12.0 \times \varnothing 7.0 \times 1.0$ Cu	5
305403	Ci IV8 Piston Trapez (Service)	12
305544	Burst disc 48 MPa ± 2 MPa (480bar)	5
2260152	O-ring 26.0x1.5 PU75	10



Pos 5	Item 2071166	7.1x1.6mm
Pos 9	Item 2251162	25.1x1.6mm
Pos 6	Item 2141162	14.1x1.6mm
Pos 7	Item 2171162	17.1x1.6mm
Pos 8	Item 2061162	6.1x1.6mm
Ci MT	Item 2260152	26.0x1.5mm

Document:
305404 Ci IV8 Service kit box

Category:
Tools & Service

Id: NST
Rev:2022.09.06



Vølundsvvej 17
DK- 3400 Hillerød
Tel +45 7022 2769
www.fire-eater.com

Text

1
2
3
4
5
6
7
8
9